




**Replacement Spring Kits
for your maintenance efforts**



All these springs need to be replaced periodically

Part # WSPGKIT6

Replacement Springs for a Morgan Solution Brush Holder system for Hitachi Generators

Brush springs wear out over time and need to be replaced. Just because your springforce is in specificatn does not mean they have the proper dynamic response. It is recommended to replace every 5 years

- Kit contains all springs required for 1 turbine
- Prevents eneven brush pressure and prevents selectivity
- Allows for uasy transport to the job site

**Kit contains: 18 Phase springs (W61050105)
4 Ground springs (W61051914)**